



Effective Date: 05/18/2018

Q248: Use of Cross-Reference Documents to Identify AR Documents Superseding Pratt & Whitney (P&W) Documents

Aerojet Rocketdyne (AR) suppliers shall not use P&W specifications, P&W supplements to AMS standards, P&W quality standards, P&W inspection methods, or the P&W Material Control Lab (MCL) Manual in support of AR Purchase Orders. These P&W documents have been superseded by AR documents.

AR suppliers shall use the following cross-references to identify AR documents superseding P&W documents:

- RF0008-000 Cross-reference Index for Heritage P&W Quality Procedures, Methods & Standards
- RF0004-526 Cross Reference List for Heritage Pratt & Whitney Specifications

Specific P&W document supersessions include the following:

- RQPWA300 Control of Materials, Processes, and Parts supersedes PWA300 and PWA-SP300
- RF0008-104 MATERIAL CONTROL MANUAL supersedes the P&W Material Control Lab (MCL) Manual

The above listed documents are available through the Supplier Portal Gateway or from the applicable Supply Chain representative.

This document is an integral part of the contract (purchase order) in which referenced. **Applicable Revision:** The revision in effect at the time the purchase order is placed.